

Park System Analysis and Service Area

Morton Elementary
506 Morton Street

Park Component	Condition			Capacity			Notes
	Poor	Fair	Good	Under	At	Over	
Vegetation (Trees, shrubs, turf)		X			X		Turf dry
Play Areas	X				X		Going through remodel
Sports Fields							None at this location
Sports Courts							No outdoor court
Walks/Trails							None at this location
Play Equipment			X		X		1 large play structure
Structures							None at this location
Picnic Facilities							None at this location
Drinking Water							None at this location
Restrooms							None at this location
Parking			X		X		Paved parking lot
Lighting							None at this location
Benches							None at this location
Signage		X			X		School sign

Source: JEO Consulting Group, Inc., 2013

Table 48: Morton Elementary Park, Lexington