

Park System Analysis and Service Area

PIONEER PARK
15th Street and Lincoln Street
2.1 acres

Park Component	Condition			Capacity			Notes
	Poor	Fair	Good	Under	At	Over	
Vegetation (Trees, shrubs, turf)			X		X		Turf dry, mature trees throughout park
Play Areas			X		X		Large open green space
Sports Fields							None at location
Sports Courts		X			X		1 basketball court
Walks/Trails							Perimeter sidewalk
Play Equipment		X			X		Large play structure, 2 swing sets
Structures		X			X		1 picnic shelter
Picnic Facilities		X			X		Picnic tables, 2 grills, trash cans
Drinking Water	X					X	Hydrant only
Restrooms	X				X		1 permanent restroom and 1 portable toilet
Parking							On-street parking
Lighting							None at location
Benches			X		X		Benches at edge of the play structure
Signage			X		X		Located in southeast corner
Miscellaneous			X		X		Memorial

Source: JEO Consulting Group, Inc., 2013

Table: 43: Pioneer Park

Pioneer Park



Google earth

feet 300
meters 90



LEGEND

- ① Restrooms
- ② Play Structure
- ③ Swing Set
- ④ Basketball Court
- ⑤ Picnic Shelter

Figure 40: Pioneer Park, Lexington